TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 240640

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A. Boyer, For: Willis Ausland, Oreg. State Hwy. - January, 1942 - C.S. File 36/18 - Volume 4 Page 86

Set - ½" Galv. I. Pipe, from which
26" Fir bears S.8°E., 72.2 ft.
26" Fir bears N.37½°E., 63.0 ft.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike Stone - November, 1962 - C.S. File 49/123-50

Found - ½" Iron pipe set by Boyer.
Rotten & burned fir stump S.8°E., 72.2 ft. charred old face visible.
Rotten & burned fir stump N.37½°E., 63.0 ft. No markings found.
Set brass cap alongside pipe mkd: County Surveyor's Office T25S R6W Center ¼ S 5 1962
New BT - 17" D.Fir N.40°W., 188.2 ft. mkd. C ¼ S5 CS BT.
No other trees near. Fence corner, fences E. & N. bears E 1 ft

---

Mark Smalley - For: Roseburg Forest Products - April 1998 - M 128-74

Found - 1962 County brass cap on iron pipe & ½" galvanized Iron pipe.
22" Fir, N.40°W., 188.2', healed.
Rotten stump, S.8°E., 72.2'
Rotten stump, N.37½°E., 63.0'
Scribed - 9" B.Oak, N.19°E., 30.3', "C ¼ BT"
10" W.Oak, N.68°E., 53.5', "C ¼ BT"
9" Fir, N.80°W., 32.0", "C ¼ BT"