TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3820)

Set ¼ sec. post, from which
A W.Oak, 15" dia. bears N.35°W., 359 lks. dist.
A W.Oak, 26" dia. bears N.12°E., 853 lks. dist.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike Stone - July/Aug. 1963 - C.S. File 49/123-98

Found - 33" W.Oak N.35°W., 235.9 ft. Cut open & found good scribing "BT".
No trace of NE bearing tree.
Set brass cap at cor. mkd: County Surveyors Office, 1963
T25S R6W ¼ S11|S12
New BTs - 6" W.Oak N.73°E., 20.2 ft. mkd: ¼ S12 CS BT.
6" W.Oak N.50°W., 112.2 ft. mkd: ¼ S11 CS BT.
Corner falls on grassy hillside (pasture) 25 ft. west of fence line running N.35°W., S.35°E.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - Dec. 2, 1997 - C.S. 64/78-32

Mon. FD.- 2½" brass cap on a 1½" O.D. iron pipe, badly bent north, protruding 11" out of ground. (1963)
Bt's Fd.- 15" now 36" dia. W.Oak, with a previously opened rotted blaze, no scribing visible, bears N.35°W., 235.9' agrees with rec.) OBT
6" now double trunk 11" dia. 10" high W.Oak rec. N.73°E., 70.2', hits SE trunk apparently cut below blaze. 1963
6" now 7" dia. W.Oak BT has grown into a fence line, unable to see a blaze, bears N.50°W., 112.2' agrees with rec.) 1963.
Mon. Set- BC/IP is straightened and returned to plumb position, protrudes 4" above ground.
New Accessories -
9" dia. W.Oak double blazed and scribed "¼ S12 CS BT", bears N.70°E., 19.6'. (note: this is NW trunk of 1963 BT).
11" dia. W.Oak double blazed and scribed "¼ S 12 CS BT", bears S.56½°E., 43.6'.
Fence line noted in 1963 renewal now nearly gone.

---

continued next page

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DCSO-GIS Corner visitation - 7/8/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - BC/IP - 1.25"
Comment - (needs) rehab