TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853 (DCSO records, Volume 9 Page 3828)

Set post (at foot of hill) cor. to secs. 27, 28, 32 and 33, from which
A Y.Oak 18" dia. bears S.8¼°W., 1202 lks. dist.
A W.Oak 16" dia. bears N.79¼°E., 916 lks. dist.
Made trench as per instructions.

Milo E. Godfrey, Dep. Co. Surveyor - Vernon Tracy; M. Stone June 1963 - C.S. File 49/123-78

Found - 40" B.Oak S.8¼°W., 793.3 ft. Cut open & found good scribing "B". North side of tree entirely dead.
No trace of NE bearing tree.
Set - Brass cap at cor. mkd: County Surveyors T25S R6W S28 S27 Office, 1963 S33 S34
New BTs - D.Fir S.35½°W., 280.6 ft. mkd: T25S R6W S 33 CS BT.
D.Fir S.14°E., 295.7 ft. mkd: T25S R6W S34 CS BT.
No trees near in Sections 27 or 28.
Cor. falls in N. & S. fence line 236.5 ft. North of 4 way fence corner.

Found OK, April 1991 - M 113-11
Found OK, April 1994 - M 118-80.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/28/2002 - C.S. File 66/32-11

Found - 1963 DCSO brass cap/iron pipe in N-S fence line protrudes 12" out of ground.
38" dia., D.Fir with a fully healed single blaze bears S.35½°W., 280.6 ft. 1963
1963 SE BT now gone
OBTs not looked for.
New - 25" dia., D.Fir bark scribed "T26S R5W S32 CS BT" bears S.4½°W., 245.7 ft.
18" dia., Apple in S'ly R/W fence, double blazed & scribed "X S28 CS BT" bears N.7°W., 701.0 ft.
No trees east of line.
Compass decl. 17½°E.

Fd. Ok by Carl Sweeden, 3/2003 - M141-72