TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4134)

Set a conglomerate stone 18x2x8", 6" in the ground (solid bedrock prevent setting deeper) for cor. of secs. 3, 4, 9, & 10 mkd with 5 notches on S & 3 notches on E edge, from which
A fir, 40" dia. bears N.22°E. 131 lks. mkd: T26S R1W S3 BT
A fir, 28" dia. bears S.49°E. 69 lks. mkd: T26S R1W S10 BT
No trees within limits in secs. 4 & 9. Raise a mound of stone 2½ ft. base, 1½ ft. high, W of corner. Pit impracticable.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1970 - C.S. File 52/77-24

Found - Corner Stone, tipped over. Also Mound of Stone as described West of Corner.
Orig. 40",now 41" Fir Snag, N.22°E. 86.5 ft., scribe visible on unhealed blaze.
Orig. 28", now 32" Fir, alive, S.49°E. 45.5 ft., shows good scar, we tag

Set - Brass Cap at Car. Mkd: County Surveyors Office 1970

T 26 S R 1 W

S 4	S 3
S 9	S 10

New BT - 36" D.Fir N.25°E. 106.5 ft. mid: "T26S R1W S3 CS BT"
No trees available in sections 4 & 9 due to solid rock bluffs.
This corner lies at top of bluff 30 ft. high. Waterfall approx. 200 ft. high bears N.83°W. approx. 400 ft. distance.