TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #55 dated March, 1855 (DCSO Records, Volume 10 Page 4357

Set ¼ sec. post, from which
A W.Oak 10" dia., bears S.18°W., 510 lks. dist.
An Ash 5" dia., bears S.7°E., 495 lks. dist.

Will P. Heydon, Co. Surveyor - For: John Watson; Monroe Whittow - Jan. 13-16, 1896 - Vol. 2 Page 61 & (Vol. 2 Pg. 285)

Set the ¼ post from the stumps of the original witness trees and also make new witness trees, to wit:
A W.Oak 20" S.11°E., 657 lks.
An Ash 16" N.1°30'W., 550 lks.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - March 1966 - C.S. File 54/7-46

Found - 1" steel shaft at corner, fences N, S, and W.
No trace of original BTs nor BTs recorded by Heydon.
Obtained Affidavit from J.C. Livington, stating he was present when shaft was set by Ben B. Irving in 1932 on Cooper survey. See C.S. File 37/78. Signed Affidavit in C.S. File 54/7
Set brass cap at cor. mkd: County Surveyors Office, 1966
T26S R3W ¼ S34|S35
Set brass cap alongside shaft in mound of stone.
New BTs - 16" Pine N.12°E., 70.3 ft. mkd. ¼ S35 CS BT.
7" Cedar N.2°W., 18.1 ft. mkd. ¼ S34 CS BT.
Corner lies at fence corner above described, on barren, rocky

---

Found OK, BLM resurvey by Berry, Popken and Carlson, June, 1972 to April 1975. Group #768 - (DCSO records, Volume 37 Page 15395)

Found OK, Bureau of Land Management resurvey by Wayne L. Rogers, Group #1058. Survey June/August 1981 (DCSO records, Volume 45 Pages 17438-39.

FD. OK, L. Dolan, April, 1986, M 100-67

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 1/23/2008 - C.S. File 67/25-10

Fd. Ok both BTs intact as per 1966 renewal.