TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 039010

PRIMARY CORNER DESCRIPTION NE Cor. Tyrell DLC #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post from which
A B.Oak 10" dia. bears N.3°W., 15 lks.
A B.Oak 4" dia. bears S.2°W., 72 lks.

James W. Byron, Deputy Co. Surveyor, September, 1954
C.S. File 46/74 (pgs 36-37) and R.M. 1-14

We can find no evidence of original corner. Neither original BT. found. Point for corner located by proportional measurement on a true line between Meander Corner & Northeast corner of Section 14.
Set - 1" x 30" I.P. with brass cap at corner point mkd:
County Surveyor's Office, N.E. Corner DLC 39 | T26S R5W | 1954
Blazed and Scribed:
13" W.Oak S.23°33'W., 83.5 ft. mkd. N.E. corner Cl 39 CS BT.
7" B.Oak S.89°40'W., 14.4 ft. mkd. N.E. corner Cl 39 CS BT.

Douglas Co. Surveyors Office - Milo Godfrey & crew - 2/5/1964
(added 6/30/2022) - C.S. File 49/125-31

Brass cap still in good condition.
Both BTs still alive & standing but 7" B.Oak may be dying

Found OK, Oct. 1985, Kris DeGroot, M 99-55