TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 19 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 4968)

Set ¼ sec. post, from which
A Laurel 8" dia. bears N.23°W., 30 lks. dist.
A Fir 22" dia. bears S.45°E., 5 lks. dist.

GLO resurvey, by Elmer F. Strickler, Contract #36 dated March 14, 1917, Special Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Page 5032)

Apportioned Distance, Set an Iron post, 3 ft. long 1" dia. 26" in the ground, for qr. cor. of sec. 19 only, T27S R3W, with brass cap mkd.

¼
S19
1917

from which
A Fir 40" dia. bears N.13°E., 21 lks. dist. mkd. ¼ S19 BT.
A Fir 50" dia. bears S.87°E., 52 lks. dist. mkd. ¼ S 19 BT.
This cor. is 460 ft. below the sec. corner.

Doug. Co. Surveyors Office - Gary L. Langlitz; Stephen J. Flause - Sept. 19, 1977 - C.S. File 59/40-18

Found - 1917 GLO brass cap on 1" I.P. 20" long, loosley set alongside the broken lower portion of the 1917 I.P. Cap properly marked.
40" D.Fir now 54" blowdown, bears N.13°E., 13.9 ft. We open well healed blaze & find plain scribe marks.
The remains of a 50" D.Fir now 54" rotten snag 10 ft. tall, bears S.87°E., 34.3 ft. No markings found.

Set at the location of the found 1917 Iron post, we set a 1" x 30" I.P. 27" in the ground with brass cap attached marked:

Douglas County Surveyor
1977

T 27 S
S 19 R
1/4 3
W

and deposit remains of 1917 I.P. alongside.
New BTs - 18" D.Fir double trunked at the base bears N.69°W., 39.2 ft. scribed "W 1/4 S19 R3W CS BT" on a double blaze. (Cont. Next Page)

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION West ¼ Cor. for Sec. 19 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

10" Hemlock bears N.53°E., 32.0 ft. scribed "1/4 S19 CS BT" on a double blaze.

Fd. Ok by K Hoffine 3/2007 - M152-54

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 3/10/2008 - C.S. File 67/25-31

Fd. 1977 DCSO brass cap 1 live BT & 2 stump.

BLM Dependent resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2189 surveyed June/Sept 2008 - (DCSO records Vol 57 Pgs 22489-90)

The ¼ sec. cor. of sec. 19 only, perpetuated by the Douglas County Surveyor's Office in 1977, monumented with an iron post, 1¼" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd.
from which the remains of bearing trees mkd. by Strickler
A roothole bears N.13°E., 13.9 ft., alongside of which is a fir trunk, 36" dia., with a healed blaze.
A fir snag, 57" dia., bears S.87°E., 34.3 ft., with a healed blaze.
and the remains of BTs mkd by the Douglas Co Surveyors Office
A hemlock, 18" dia., bears N.53°E., 32.3 ft., with a healed blaze.
A sawed fir stump, 18" dia., bears N.68¼°E., 38.4 ft., with a healed blaze.
and a new bearing tree
A cedar, 20" dia. bears S.33¼°E., 28.1 ft. mkd. ¼ S19 BT