TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5070)

Set ¼ sec. post, from which
A Laurel, 12" dia. bears N.45°E., 6 lks. dist.
A Pine, 10" dia. bears N.38°W., 39 lks. dist.

James W. Byron, Deputy Surveyor - M. Godfrey; S.A. Bilow January, 1959 - C.S. File 49/130-15

Found - Orig. 12", now partly burned Laurel snag, N.45°E., 4.0 ft. I open from inside & find good scribing "4 S".
Find stump hole that checks bearing & dist. for orig. NW BT.
Set brass cap at corner mkd: County Surveyor's Office 1959
¼ S31|S32 T27S R4W
New BTs - 21" R.Fir bears S.26½°E., 32.4 ft. scribed ¼ S32CSBT
15" Cedar bears S.7½°W., 49.7 ft. scribed ¼ S31 CSBT
(Cor. is approx. 20 westerly of fence corner)

Douglas Co. Surveyors Office - Gary Langlitz, Peter Earle - June 3, 1974 - C.S. File 56/51-14

Found - Brass cap firmly set in E-W fence line & mkd. as described by Byron. The Laurel snag noted as found in 1959 by Byron is now out of the ground & downhill from the corner, reverse scribe is still visible.
A 21" now 24" R.Fir mkd. by Byron in 1959 is alive and well-healed bearing S.26½°E., 32.4 ft. (Note: this tree will be cut in logging operations in the near future.)
A 15" now 18" I.Cedar mkd. by Byron, is alive & well healed bearing S.9°W., 49.7 ft.
New BT - 5" D.Fir bears S.58½°E., 19.3 ft. scribing "1/4 S 32 CS BT".