TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5046)

Set ¼ sec. post, from which
A W.Oak 5" dia. bears S.35°W., 24 lks. dist.
A W.Oak 6" dia. bears N.68°E., 59 lks. dist.

GLO survey by W.H. Byars, under Contract #376 dated January 22, 1881 (DCSO records, Volume 12 Page 5079)

Intersect ¼ sec. cor. and set new post as per instructions. from which
A W.Oak 5" dia. bears S.35°W., 24 lks. dist.
A W.Oak 6" dia. bears N.68°E., 59 lks. dist.

Bureau of Land Management Dependent Resurvey - Lynn Roseberry under Group #636. Survey May/June 1967 (DCSO records, Volume 34 Pages 14192-93)

Point for the standard ¼ sec. cor. of sec. 32 only, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long 2½" dia. 24" in the ground, with brass cap mkd:

S C
T 27 S R 4 W
¼ S 32
1967

from which
A Fir 35" dia. bears N.55½°E., 247 lks. dist. mkd. ¼ S32 BT.
A Fir 15" dia. bears N.31¾°W., 43½ lks. dist. mkd. ¼ S32 BT.
From this point, an orig. bearing tree now displaced by road construction, bears N.63½°W., 33 lks. dist., an uprooted Fir, 18" dia. with faint scribe marks S BT visible on bark. There is no evidence remaining of the original position of this tree.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/10/2000 - C.S. File 66/14-21

Found OK.