TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5049)

Set ¼ sec. post, from which
A Dogwood 7" dia. bears N.85°W., 8 lks. dist.
A Cedar 9" dia. bears S.81°E., 6 lks. dist.

Milo E. Godfrey, Deputy Co. Surveyor - Stoffel; Stone and Darby - April/May 1964 - C.S. 53/33-67

Found - Dogwood, badly rotted, N.85°W., 5.3 ft., opened & found fragments of reverse scribing on over-growth of old face.
Portion of stump and roots (badly rotted) of Cedar, S.81°E., 4.0 ft.
Set brass cap at cor. mkd: County Surveyors Office, 1964
T27S R4W ¼ S35|S36
New BTs - 25" Hemlock S.74°W., 28.4 ft. mkd: ¼ S35 CS BT.
53" D.Fir N.56°E., 24.0 ft. mkd: ¼ S36 CS BT.
Corner lies on very steep north slope approx. 1 chain south of small stream running west.

David Edwards - For: Sierra Pacific Industries Inc. - 10/2022 - C.S. File 65/110-7

Condition report only
Found - DCSO brass cap
32" hemlock S.74°W., 28.4 ft.
53" Fir N.56°E., 24.0 ft.
Both with healed blaze.