TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 600339

PRIMARY CORNER DESCRIPTION West ¼ cor. for Sec. 24 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5050)

Set ¼ sec. post for 23 and 24, from which
A R.Fir 16" dia. bears N.87°E., 7 lks. dist.
A Maple 6" dia. bears S.45°W., 12 lks. dist.

Resurvey & Retracement Govt. Land Office, Elmer F. Strickler, under Special Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Page 5086)

Set an iron post 3 ft. long 1" dia. 26" in the ground for ¼ cor. of sec. 24 only with brass cap mkd: ¼ | S 24 1917
from which
A Fir 40" dia. bears N.67°E., 55 lks. dist. mkd. ¼ S24 BT
A Fir 40" dia. bears S.73°E., 33 lks. dist. mkd. ¼ S24 BT
This cor. is 90 ft. below the spur.

Milo E. Godfrey, Deputy Co. Surveyor; Wm. Stoffel; Mike Stone November 1963 - C.S. File 53/33-35

Found - I.Pipe with brass cap set in 1917 survey.
40" Fir S.73°E., 21.8 ft. shows very plain axe scar.
Tree alive and in good condition.
Stump of 40" Fir N.67°E., 36.3 ft. shows good scar.
Did not open.
New BT - 24" D.Fir S.30°E., 40.1 ft. mkd. ¼ S24 CS BT.
Corner lies on steep N. slope approx. 150 ft. N. of ridge top.

Corner found and used in Dependent Resurvey Bureau of Land Management, Glenn Baughman, Contract #52500-CT5-1116, Survey Oct.-Dec. 1975 (DCSO records, Vol. 39 Page 15788)