TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ Sec. post, from which
A Y.Oak, 12" dia. bears N.13°W., 14 lks. dist.
A Y.Oak, 12" dia. bears S.23°E., 14 lks. dist.

Byron & Godfrey, Deputies - Nov. & Dec. 1963 - C.S. 53/38-6

Found - Both orig. BTs. Each BT has rotted center.
12" now 20" B.Oak, S.33°E., Not S.23°E., 9.2 ft. shows good scribe marks.
12" now 24" B.Oak, N.13°E., 9.2 ft. shows good scar.
Set - Brass cap at cor. mkd: County Surveyors Office, 1963
¼ S28 T27S R5W
S33
Note - Corner at N-S fence.
New BTs - 14" R.Fir bears S.68°W., 39.5 ft. scribed ¼ S33 CS BT.
12" B.Oak bears N.75°W., 41.5 ft. scribed ¼ S28CS BT

Found OK April 22, 1980 - Fd. May 21, 1984 by R. Thompson, M 96 - 58

Doug. County Surveyors Office - Randall Smith; Stephen Flause April 28, 1993 - C.S. File 64/43-21

CORNER REPORT ONLY
Found - 2½" 1963 DCSO brass cap on a 1½" O.D.I.P. protruding 12" above ground.
12" now 22" dia. B.Oak with a previously opened blaze, no scribing visible, bears S.33°E., 9.2 ft. (agrees w/record 1963 Byron) Orig. BT.
12" now 25" dia. B.Oak with a previously opened blaze, no scribing visible, bears N.13°W., 9.2 ft. (agrees w/orig. rec., brg. recording error in 1963 Byron visit) Orig. BT.
12" now 16" dia. B.Oak with a fully healed double blaze, bears N.76½°W., 40.8 ft. (Rec. N.75°W., 41.5 ft.) 1963 Byron BT.
14" now 16" dia. D.Fir with a fully healed double blaze bears S.68°W., 39.5 ft. (agrees w/rec.) 1963 BT.
Corner lies on top of knob of a N-S ridge.

Found OK by C. Sweeden, April 2004 - M144-56
Fd. OK by Kris DeGroot, 6/2009 - 2009-0034A&B