TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5807)

Set ¼ sec. post, from which
A Cedar 18" dia., bears S.1°E., 24 lks. dist.
A Fir 24" dia., bears S.60°W., 19 lks. dist.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - Wit: J. Clark and R. Hendrickson - Aug. 24, 1962 - C.S. File 51/163-11

Found - 18" Cedar S.1°E., 24 lks. (now 36")
24" Fir S.60°W., 19 lks. (now a stump)
Set 4" x 4" x 4 ft. Post.
Scribed- 4" Fir S.48°W., 10.0 ft.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 6, 1966 - C.S. File 52/79-23

Found - 18" Cedar now 39", S.1°E., 15.8 ft. scribe visible "4S".
4" D.Fir now 6", S.48°W., 10.0 ft.
24" Fir stump, now gone.
Set Brass cap at cor. mkd: County Surveyors Office
T 28 S R 8 W
¼ S28|S27
1966
All BTs in good condition. Do not mark new trees.

Cor. Fd. and Used in BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15074)

Cor. Fd. and Used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15575-76)

Found OK by D. Edwards, Jan. 2003 - M141-66

Used on BLM retracement by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2300, surveyed June 2006 - (DCSO records Vol. 56 Page 22274 & Plat T28-8 2011-2)