TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1; & 36 T28-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 24 pg 10253 & Vol. 25 Page(s) 10623-4)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor., with brass cap marked ¼ S 36 / S 1 / 1921

A cedar, 42" dia., bears N.23°E., 31 lks., mkd: ¼ S36 BT.
A fir, 14" dia., bears S.2°E., 10 lks., mkd: ¼ S1 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - July 1, 1974 - C.S. File 57/2-1

Found - 1" Iron pipe with brass cap attached, bent over but still firm in the ground, marked US General Land Office Survey ¼ S36 Sl 1921, from which:
An orig. 42" now 30" Incense Cedar bears N.23°E., 20.5 ft alive and well healed.
An orig. 14" now 12" D.Fir bears S.2°E., 6.6 ft. alive and well healed.

We remove the brass cap, straighten it and reset it " inches in the ground at its present position.
This corner lies on a south slope, approx. 100 ft. north of US Forest Service Road No. 284 and approx 500 ft. east of the concrete bridge crossing over Quartz Creek on Road No. 284.