TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6251)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for ¼ sec. cor. with brass cap marked: ¼ S 1
S 12
1917

from which
A Fir 30" dia., bears N.45°E., 17 lks. dist., mkd. ¼ S1 BT
A Pine 12" dia., bears S.23°W., 55 lks. dist., mkd. ¼ S12 BT.

Douglas Co. Surveyors Office - Dennis Gaylord, U.S.F.S. (Deputized by the County) -Wit: Randal Lopez - April 27, 1978 - C.S. File 59/46-40

Found - 1917 GLO brass cap on a 1" I.P. set solidly in ground stamped U.S. General Land Office Survey ¼ S1 S12. I ADD "T29S R2W" to brass cap.
30" now 33" D.Fir bears N.45°E., 11.22 ft. Has a healed scar.
17" W.Pine bears S.23°W., 36.6 ft. (Rec. 36.3 ft.) Has a healed scar which has been recently chopped into about 1".

Placed County BT signs on both trees. Corner lies 75 ft. North of F.S. Rd. #2929.
No new monument or accessories set.