TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 975110

PRIMARY CORNER DESCRIPTION Cor. #12 H E S No. 141

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11754)

Cor. No. 12, identical with Cor. H/3 of listing survey, a Maple tree 24" dia., mkd. and witnessed as described by the listing surveyor.
I blaze and scribe the tree "12 H E S 141" on W. face, for Cor. 12; from which
A Fir 16" dia., bears S.3°30'E., 26 lks. dist.
A Fir 16" dia., bears S.37°30'W., 34 lks. dist.
Both trees blazed and scribed 12 H E S 141 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V Perron, crew - Nov. 21, 1969 - C.S. File 54/96-19

Found - Hole where old corner tree stood.
Orig. 16" now 30" W.Fir, alive S.3½°E., 17.2 ft., shows scar. We tag.
Orig. 16" now 28" W.Fir stump, S.37½°W., 322.4 ft., we open and find scribe.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 2 W
Cor. #12 HES 141
1969
New BT - 12" W.Fir S.57°W., 24.0 ft. mkd. 12 HES 141 CS BT.
This corner lies on flat near foot of mountain.

Survey by James Artman - For: U.S.F.S. - Nov. 1990 - C.S. File 63/104-69

Found - 1" Iron pipe with a 2½" brass cap 12" above ground.
Orig. BT,30" W.Fir stump bears S.3°30'E., 17.2 ft., rotted.
Orig. BT, 28" W.Fir stump bears S.37°30'W., 22.4 ft., rotted.
16" W.Fir snag bears S.57°W., 24.0 ft. with healed blaze. 1969 BT.
New BTs- 16" Yewwood bears S.64°W., 11.8 ft. scribed "12 HES 141 BT" with alum. tag mkd. "ARTMAN RLS 2268" nailed flush to BT face.
9" Yewwood bears N.31°E., 23.0 ft. scribed "12 HES 141 BT" with alum. tag mkd. "ARTMAN RLS 2268" nailed flush to BT face.
Painted and tagged all BTs.