TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 700501

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only, T29-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6229)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for ¼ cor. of sec. 18 only, with brass cap marked:

¼
S18
1917

from which

A Fir 20" dia., bears N.31°15'E., 65 lks. dist. mkd. ¼ S18 BT.

A Fir 20" dia., bears S.84°E., 46 lks. dist. mkd. ¼ S18 BT

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. File 52/126-84

Found brass cap at corner and both BTs as recorded. NE. BT, now snag, shows scribing. SE. BT, now down.
New BT - 20" Fir bears S.24°E., 20.2 ft. scribed ¼ S18 CS BT.
No other BTs. scribed.

Tony Hostetter - For: Seneca Jones Tbr Co - 4/2006 - M150-38

Found - 1917 brass cap as described by Byron in 1962 (C.S. File 52/126)
Fir BT @ N.31°15'E., is now a very rotten stump.
24" Fir stump, face evident, BLM tag, bears S.24°E., 20.2 ft. (Note: This is the same BT as described as being S.50°E., 19 lks from the SE corner of sec. 12)

New BTs- 8" Fir, scribed "S18 ¼ BT" bears N.49°E., 19.2 ft. to spike.
10" Fir, scribed "S18 ¼ BT" bears N.17°W., 18.7 ft. to spike.