TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

---

GLO survey by Dennis Hathorn, Deputy Surveyor, under Contract #73 dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6385)

---

Set ¼ sec. post, from which
A Fir 18" dia., bears N.2°E., 66 lks. dist.
A Fir 12" dia., bears N.15°W., 60 lks. dist.

---

GLO survey by W.F. Briggs, Deputy Surveyor, under Special Instructions dated Jan.18, 1899 - (DCSO records Vol. 15 Page(s) 6415)

---

¼ S. cor. post gone.
Witness trees standing.
Reestablished corner in the original position by setting a new post mkd. ¼ S7 on W.; S8 on E. faces.

---

Ben B. Irving - Jim Byron; Ray Irving, crew - July 23, 1953 -C.S. File 45/234

---

Position identified from stump of OBT, 12" Fir N.15°W., 60 lks., tree 36" when cut.
Blazed and scribed two new BTs:
12" Fir N.66°W., 9.3 ft. mkd. ¼ S7 CS BT.
12" Fir S.14°E., 42.3 ft. mkd. ¼ S8 CS BT.
Set 1" Iron pipe with brass cap mkd. County Surveyors Office

¼ Cor.
Sec. 7 | Sec. 8 Douglas

---

Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - April 1963 - C.S. File 52/126-116

---

Found - Brass cap at corner and both BTs. NE. BT now down.
New BT - 13" Cedar bears N.18°W., 46.8 ft. scribed ¼ S7 CSBT.

---

Fd. OK, Nov. 1987 by D. Bentz - M 105-19

---

Fd. and used in BLM survey by Boyd Peterson, under Group #1394, surveyed Aug. 1987/Jan. 1988 - (DCSO records Vol. 48 Page(s) 18517-18)

---

Fd. OK, Dec. 1994 by R. Dolan - M 121-29
Fd, OK, March 1998 by D. Edwards - M 128-32

---

Fd & used on BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19796-7)