TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 045050

PRIMARY CORNER DESCRIPTION Int. SE Cor. A.D. Willis DLC #45

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey)

Set a post from which
An Ash 4" dia., bears West 39 lks.
A Fir 15" dia., bears South, 49 lks.

Frank Cain - April 28-29, 1916 - Vol. 2 Pg. 201

Interior L corner post (Fir) marked C.S. C.45 T29S R6W, from which
A Fir 12" marked C.S. C.45 T29S R6W bears S.15°W., 49 lks.
A Fir 30" marked C.S. C.45 T29S R6W bears N.6°W., 24 lks.

Ben B. Irving, Deputy Co. Surveyor - Jan. 24, 1929 - C.S. File 22/33; Vol. 3 Pg. 290; M 6-1

This corner found as described. Drive car axle for corner and remarked BTs on bark. Stake at new corner axle in mound of stone 2½ ft. dia. x 1 ft. high.

Corner looked for, <u>not found</u> - DCSO - April 19, 1971 - C.S. File 49/139-140

Douglas County Surveyors Office - Randall Smith & Stephen Flause - Feb. 7, 1996 - C.S. 64/66-4

Mon. Fd. - None
BT's Fd. - None
Looked into 3 stumps, most stumps in surrounding area cut at ground no evidence found.