TOWNSHIP 30 RANGE 1E POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract dated June 7, 1922 - (DCSO records Vol. 26 Page(s) 11007-8)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor., with brass cap marked

¼ S 29 / S 32

1923

from which

A cedar, 12" dia., bears N.51°E., 14 lks., mkd: ¼ S29 BT.
A fir, 38" dia., bears S.27°W., 37 lks., mkd: ¼ S32 BT.

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy - E. Rueben Scott - July 7, 1980 - C.S. file 61/11-6

Found - A 1923 USGLO brass cap on a 1" iron post and 3 ft. long , properly mkd, protrudes 17" from ground, monument is slightly loose and leaning southwest.
Orig. 12" Cedar now a 13" cedar, bears N.48½°E., 9.4 ft. (rec. N.51°E., 9.2 ft.) This tree has a partially healed single blaze with "4 S 29 B" visible.
An orig. 38" now a 40" D. Fir bears S.28½°W., 24.4 ft. (rec. S.27°W., 24.4 ft.) This tree has a well healed single blaze with no scribing visible.

Set - Because monument may be disturbed by road construction, it is not reset but 2 new bearing trees which will be safe from planned road construction are marked:

BTs - A 16" Madrone bearing N.32°E., 46.6 ft. is bark scribed "¼ S29 CS BT".
An 18" W.Fir (with a leaning curved trunk) bearing N.48°W., 43.8 is scribed "¼ S29 CS BT". on a double blaze.

Both trees are tagged with DCSO BT tags. No other suitable trees available until road construction is complete.