TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6939)

A Fir 3" dia., which I mark ¼ S. on W. face, for ¼ sec. cor., from which
A Chinquapin 6" dia., bears S.18°W., 6½ lks. mkd. ¼ S BT.
A Fir 30" dia., bears S.22½°E., 30¾ lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - July 25, 1960 - C.S. 49/47-16

Found - Orig. 30" now 40" Fir stump S.22½°E., 20.3 ft. I open and find good scribing "4".
Orig. 6" now 12" Chinquapin S.18°W., 4.3 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 3 W
¼ S3|S2
1960
New BTs- 10" R.Fir bears N.41°E., 20.9 ft. scribed ¼ S2 CS BT
Rescribe 12" Chinq. S.18°W., 4.3 ft. "¼ S3 CS BT".

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Sept. 1, 1967 - C.S. File 54/52-7

Found - 1960 DCSO brass cap at ¼ corner.
12" Chinquapin S.18°W., 4.3 ft., scribe visible "¼ S3 CS BT"
10" Fir N.41°E., 20.9 ft scribe visible "¼ S2 CS BT"
New BT - 7" D.Fir N.51°W., 17.4 ft. scribed ¼ S3 CS BT.

Fd. OK H. Johnstone, 10/1980 - M86-6

Ron Quimby - 2/2012 - C.S. File 65/76-20

Found - DCSO brass cap, 12" above ground.
40" Fir stump S.22½°E., 20.3 ft. prev. opened.
12" Chinquapin S.18°W., 4.3 ft. down & rotten face visible.
20" D.Fir N.41°E., 20.9 ft. good scar.
22" D.Fir N.51°W., 17.4 ft. good scar.
New - 10" D.Fir S.38°W., 32.0 ft. scribed ¼ S3 BT on single blaze.
6" D.Fir S.27°E., 18.1 ft scribed ¼ S2 BT on single blaze.
Note - Corner is on an east facing hillside approx. 650 south of CC Corner 3|2