TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7246)

Set ¼ sec. post, from which
A Fir 6" dia., bears N.25°E., 8 lks. dist.
A Fir 30" dia., bears S.20°W., 8 lks. dist.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #571, surveyed May/June 1965 - (DCSO records Vol. 33 Page(s) 13865)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 23" in the ground, with brass cap mkd: T 30 S R 7 W

¼
S 21 | S 22
1965

from which
A Fir 36" dia., bears S.45°E., 25 lks. dist. mkd. ¼ S22 BT.
A Fir 33" dia., bears S.58°W., 77 lks. dist. mkd. ¼ S21 BT

BLM resurvey by Lance Bishop, Cadastral Surveyor, under Group #1170, surveyed Sept. 1983 - (DCSO records Vol. 47 Page(s) 17841)

The ¼ sec. cor., monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with 1965 BLM brass cap
from which the remains of bearing trees mkd. by Jelley:
A Fir stump 40" dia., bears S.45°E., 25 lks. dist., no marks visible.
A Fir 38" dia., bears S.58°W., 77 lks. dist., with healed blaze.
and a new bearing tree:
A W.Fir 14" dia., bears N.53½°W., 43 lks. dist. mkd. ¼ S21 BT.
No suitable tree available in sec. 22.