TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7356)

Set a stone 14x9x5", 9" in the ground for ¼ sec. cor. mkd. ¼ on North face, from which
An Oak, 9" dia., bears N.62°W., 44 lks., mkd: ¼ S BT.
A Live Oak, 15" dia., bears S.22°W., 34 lks., mkd: ¼ S BT.

Reported as not found, 10/1965 - DCSO, VRT - C.S. 53/67-31

Douglas Co. Surveyors Office - Gary Langlitz - P. Earle - 3/26/1974 - C.S. File 56/49-7

Found - Orig. 9" now 14" forked B.Oak with scribing "¼" visible on newly opened blaze.
19" live oak, blazed portion rotten and burnt-out, no marks found.
No trace of original stone.

Set - Brass cap mkd: COUNTY SURVEYORS OFFICE 1974 T30S R8W ¼ S 30 / S 31
at record bearing and distance from original NW bearing tree (N.62°W., 29.0 ft.)
The aforementioned 19" live oak bears S.22°W., 19.0 ft. (rec. S.22°W., 22.4 ft.) Note The slope distance to this tree is 22.4 ft at 32°. I do not mark this tree.

New BT - 8" D.Fir bears N.70°E., 15.2 ft. scribed ¼ S30 CS BT
This corner lies approx. 75 ft. south of a rock bluff, course NW-SE.