TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7320)

Marked a fir 7" in dia., ¼ S on the W side for the ¼ sec. cor. from which
A cedar, 18" dia., bears N.30°W., 18 lks., mkd: ¼ S BT.
A laurel, 12" dia., bears N.33°E., 45 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - April 1965 - C.S. File 53/67-49

Found - ¾" I. Pipe & one Orig. BT: (No record of I. Pipe)
Orig. 18", now 40" Cedar, down, N.30°W. 1l.9 ft., prev. opened & face burned. We open lower & find "BT" scribe.
Other BTs gone, we find stump hole at correct bearing & distance.
Set brass Cap at Corner mkd: County Surveyors Office, 1965
T308 R8W ¼ S14|S13
New BTs- 6" W.Fir N.45°E. 100.9 ft. mkd: S13 CS BT.
9" Pine N.7l½°W. 181.5 ft. mkd: S14 CS BT.
Note - This corner lies in logged area approximately 500.0 ft. N. of edge of timber course E & W.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group No. 2139, surveyed July/Aug. 2006 (DCSO records Vol. 57 Page(s) 22541)

The ¼ sec. cor. of secs. 13 and 14, remonumented by Tracy, in 1965, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees
A roothole bears N.45°W., 11.9 ft., with fallen cedar trunk, 40" dia., lying alongside, with no marks visible on an opened blaze. (Record, N.30°W.)
and a bearing tree mkd. by Tracy
A fir, 22" dia., bears N.43°E., 100.0 ft., with a healed blaze.
and new bearing trees
A fir, 12" dia., bears S.54¾°E., 3.8 ft., mkd. ¼ S13 BT.
A fir, 11" dia., bears S.39¾°W., 14.5 ft., mkd. ¼ S14 BT.