TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7422-3)

Set a stone 16x12x10", 12" in the ground for cor. of secs. 28, 29, 32, & 33 mkd with 1 notch on S & 4 notches on E edges, from which

A fir, 17" dia., bears N.18¾°E., 49 lks., mkd: T30S R9W S28 BT.
A fir, 15" dia. bears S.57°E. 9½ lks. mkd: T30S R9W S33 BT
A fir, 15" dia., bears S.20¾°W., 36½ lks., mkd: T30S R9W S32 BT.
A fir, 15" dia., bears N.42¼°W., 37½ lks., mkd: T30S R9W S29 BT.

Douglas Co. Surveyors Office - John M. Powell - F. Jones & J. Brady - Oct. 1965 - C.S. File 53/53-3

Found - 15", now 25" Fir S.57°E. 9½ lks., opened & scribe visible, 15" Fir, now 21" S.20¾°W. 36½ lks. shows good scar.
15", now 22" Fir N.42¼°W. 37½ lks., shows good scar, found distance to be 23.7 ft.
17" now 23" Fir N.l8¾°E. 49 lks., Shows good scar.
No trace of Orig. Rock at Corner.

Set Brass Cap at Cor. mkd: County Surveyors Office, 1965 T30S R9W S29|S28 / S32|S33

All Trees listed above in good condition. Did not Rescribe.
Note - This corner is in a small draw.

Fd. Ok by K. Hoffine, 4/1995 - M119-59