TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7421)

Set a stone 14x14x10", 9" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
A fir, 16" dia., bears S.60°W., 85 lks., mkd: ¼ S BT.
A fir, 38" dia., bears N.75°E., 41½ lks., mkd: ¼ S BT.
This cor is set in a ravine course E & W.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby - Wm Stoffel - Jim Combs (C & D Lumber Co.) - Dec. 4, 1962 - C.S. File 49/100

Found - Orig. 16", now 30" Fir S.60°W., 56.1 ft., shows good scar.
Orig. 38", now 48" Fir Stump, shows good scribing "¼S" on old face.
Do not find stone at cor. which is in toe of rock road fill. .
Set -Brass Cap at Cor. Mkd: County Surveyors Office, 1962
¼ S21|S22 T30S R9W
New BTs- 16" R.Fir bears S.82½°W., 102.8 ft. scribed ¼ S21 CS BT.
24" R.Fir bears S.38°E., 90.5 ft. scribed ¼ S22 CS BT.
Note - Corner is on steep West Slope and 40 ft. West of logging Road.