TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7390

Set ¼ sec. post, from which
A fir, 12" dia., bears S.67°W. 7 lks.
A cedar, 18" dia., bears S.59°E. 19 lks.

Douglas Co. Surveyors Office - James W. Byron & crew - MFay 10, 1963 - C.S. File 49/100-80

Found - Base section of down & rotted Fir, shows good scribing "BT"
Down cedars to NE
Set brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963
¼ S15|S14 T30S R9W
New BTs- 7" fir bears S.25°E., 11.8 ft. scribed ¼ S14 CS BT
5" fir bears S.52°W., 34.5 ft. scribed ¼ S15 CS BT

FD. Ok by K. Hoffine 10/2001 - M138-79 (SE Fir now snag)

Gary Smither - For: Moore Mill & Lmbr Co.& Rsbg Resources Co. - 10/2006 - M151-57

Found - County brass cap with steel post alongside 1963 Renew, M71-5
BTs - 12" hemlock snag S.25°E., 11.9 ft. with healed face
15" D.Fir S.51°W., 34.5 ft. (Rec W.Fir) with healed face & aluminum tag
New BTs- 23" D.Fir S.4°W., 39.4 ft. To spike side center & at scribe T30R9 ¼15BT
11" D.Fir S.22°E., 24.7 ft to spike side center & at scribe T30R9 ¼14BT
6 D.Fir N.11°E., 46.3 ft. to spike side center & at scribe T30R9 ¼14BT

FD. Ok by Carl Sweeden - 11/2007 - M154-67
FD. Ok by D Edwards - 2/2020 - M176-49