TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Pgs 7600-01)

Set ¼ sec. post, from which
An Oak 18" dia., bears N.64°E., 96 lks.
An Oak 20" dia., bears S.20°W., 76 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-75

Found - 18" now 26" B.Oak N.64°E., 63.4 ft., rotted out.
20" now 28" W.Oak S.20°W., 50.2 ft., rotten face but found scribing "BT".
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
¼ S3|S2
1966
New BTs- 12" D.Fir S.27°W., 43.6 ft. mkd. ¼ S3 CS BT.
11" W.Oak N.83°E., 41.3 ft. mkd. ¼ S2 CS BT.
Very old fence line bears West about 10.0 ft.

Jonathan B. Drew, II, USFS - Report by: Andrew Hellman - Assisted by: Jacob Hunt - 8/29/2016 - C.S. File 65/93-41

Condition Report
Found - A 1¼" galv. iron pipe with a 2½" brass cap, projecting 14" above a mound of stone.
Record accessories and measurements
A 23" Oak stump with no marks visible on a rotted blaze. (N.64°E., 63.4 ft.) 1857 & 1966
A 30" Oak with no marks visible on a rotted double blaze. (S.20°W., 50.2 ft.) 1857 & 1966
A 16" fir high stump with healed double blaze. (S.27°W., 43.6 ft.) 1966 (S.27°E.) 1978
A 13" Oak with a healed double blaze. (N.83°E., 41.3 ft.) 1966
No new accessories add - No new measurements taken. Guard posts present but not measured.
Note - Clear brush from around monument and to BTs. Tie flagging to monument and guard posts, paint BT faces & a 6" band at head height.
Latitude: N.42°54'33.066" Longitude: W.122°55'21.419"
Datum: NAD83
Source: post processed resource grade, as reported by Jack Snyder.