TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Geo. W. Hyde, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7884)

Set ¼ sec. post, from which
A Fir 5" dia., bears S.68°30'E., 38 lks. dist.
A Laurel 6" dia., bears N.23°W., 12 lks. dist.

BLM resurvey by Joseph Gawron and Norman McDonald under Group #472, Surveyed June/July 1962 (DCSO records Vol. 32 Pg 13245)

The ¼ sec. cor. of sec. 32 only, determined from an orig. BT:
A Fir 18" dia., bears S.68½°E., 38 lks. dist., mkd. ¼ SB on an open blaze.
At the corner point
Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd: T 31 S R 5 W
¼ S 32
1962
from which
A Fir 15" dia., bears N.15°E., 26 lks., mkd. ¼ S32 BT.
A Fir 20" dia., bears N.57°W., 34 lks., marked ¼ S32 BT.

Survey by T.H. Mehl, III - For: Robert Dollar Co. - June 16, 1967 - C.S. File 55/15-4

Found - 1962 Brass cap and iron pipe.
18" D.Fir S.68½°E., 38 lks.
15" D.Fir N.15°E., 26 lks.
20" D.Fir N.57°W., 34 lks.
This corner is in good condition. No new accessories were set.

David Edwards - Crew: Brant Miller & Eric Sprinkle - March 2015 - C.S. File 65/87-37

Found - 1962 BLM brass capped iron pipe. Standard BC/IP
BLM BT S.68½°E. is a windfall.
The other two BLM BTs are at the rec positions but are snags.
New - A 17" dia. Fir bears N.54°E., 25.3 ft. scribed "T31S R5W ¼ S32 BT"
A 14" dia. Fir bears N.76°W., 25.46 ft scribed "T31S R5W ¼ S32 BT"
A 14" dia. Fir with a painted blaze bears S.36°E., 2.73 ft.
Measurements are to 16d nails driven side—center at root crown.
Compass Declination 15° East