TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 241100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 5 only of T32-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM survey by Joseph Gawron and Norman McDonald, under Group #472 - Surveyed, June/July 1962 (DCSO records Vol. 32 Page(s) 13259-60)

Point for the S. ¼ sec. cor. of sec. 5 only, at mid-point, longitudinally, on the N. bdy. of sec. 5.
Set an iron post, 30 ins. long, 2½ ins. dia., 24 ins. in the ground, and in a mound of stone, 4 ft. base to top, with brass cap mkd:

¼ S 5
T 32 S R 5 W
1962

from which
A Cedar 12" dia., bears S.15½°E., 35 lks. dist., mkd. ¼ S5 BT.
A Fir 10" dia., bears S.88°W., 23 lks. dist., mkd. ¼ S5 BT.

Survey by T.H. Mehl, III - For: Robert Dollar Co. - June 16, 1967 - C.S. File 55/15-4

Found - No trace of 1962 Cadastral brass cap.
10" D.Fir S.83°W. 23 lks. knocked over by logging.
12" I.Cedar S.15½°E., 35 lks. scribing buried under logs.
Set 1½ x 40" Iron Pipe, 32" into the ground, from which:
Rescribed the 12" I.Cedar "¼S RS 749 BT", four feet above ground.