TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7985)

Set Fir post 3 ft. long, 3" sq., 18" in the ground for the ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 22" dia., bears S.72°W., 24 lks. dist. mkd. ¼ S BT
A Fir 22" dia., bears N.60°E., 12 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, Jack Barnett - Nov. 5, 1964 - C.S. File 52/25-29

Found - 22" now 30" D.Fir S.72°W., 15.8 ft. badly burned snag.
22" now 34" D.Fir N.60°E., 7.9 ft. alive and shows "4 S" in bark

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 6 W
¼ S 15 / S 22
1964

New BTs -19" D.Fir S.40°W., 27.9 ft. mkd. ¼ S22 CS BT.
12" D.Fir N.10°W., 47.5 ft. mkd. ¼ S15 CS BT.

Found OK by Lang, April 1995 - M125-3

Douglas County Surveyors Office - Randall Smith & Stephen Flause - June 10, 1996 - C.S. 64/69-1

Mon. Fd.- 2½" Brass cap on a 1¼" O.D. iron pipe protrudes 7" above ground. (1964 DCSO)

Bt's Fd.- 30" dia. 20' High D.Fir snag no bark scribing found, bears S.72°W., 15.8'.
34" dia. D.fir no bark scribing found, bears N.60°E., 7.9'.
22" dia., 1½" high D.Fir stump, with a fully haled blaze, bears S.40°W., 27.9'.
20" dia., 3' high shattered D.Fir stump, scribing visible "15 CS", bears N.10°W., 47.5'.

New BT's- 5" dia., D.Fir double blazed and scribed "¼ S15 CS BT", bears N.83°W., 11.6'.
7" dia., D.Fir double blazed and scribed "¼ S22 CS BT", bears S.16°E., 15.3'.
6" dia., D.Fir double blazed and scribed "¼ S22 CS BT", bears S.76°E., 10.3'.