TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8044)

Set Cedar post 3 ft. long, 3" sq., 18" in the ground for ¼ sec.cor. marked ¼ S. on W. face, from which
A Fir 10" dia., bears N.52°W., 37 lks. dist. mkd. ¼ S BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14504)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: ¼
S 11|S 12
T 31 S R 7 W
1969
from which
A Fir 7" dia., bears S.54 3/4°E., 37½ lks. mkd. ¼ S12 BT.
A Fir 13" dia., bears S.65¼°W., 31 lks. mkd. ¼ S11 BT.

Ron Quimby - Crew: R. Olsen & J. Leonard - 9/2017 - C.S. File 65/99-8

Found - BLM brass cap (properly mkd)
16" Fir stump S.55°E., 24.8 ft. good scar.
26" Fir S.65°W., 20.5 ft. good scar.
New - 30" D.Fir N.3°W., 43.8 ft. scribed ¼ S11 BT.
12" D.Fir South 28.0 ft. scribed ¼ S11 BT.
8" D.Fir N.22°W., 10.5 ft. scribed ¼ S11 BT.
No trees to the east (clearcut)
Note - Corner is approx. 400' North of road on East facing slope area burnt 9/2017.
Compass decl. 15½°E.