TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8143)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, marked ¼ S on N side for the ¼ sec. cor., from which
A fir, 12" dia., bears N.62°E., 16 lks., mkd: ¼ S BT.
A fir, 12" dia., bears S.20°E., 12 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey - S.A. Bilow - Aug. 1958 - C.S. File 49/109-3

Found - Orig. 16", now 16" R.Fir, previously opened. Shows good scribing "¼" N.62°E. 10.6 ft.
Orig. SE BT., shows good scars. I do not open. Checks bearing & distance.
Set Brass Cap at Corner mkd: ¼ S21/S28 T31S R8W County Surveyors Office, l958
New BTs- I rescribe Orig. N.62°E., 10.6 ft. BT. ¼ S21 CS BT.
10" R.Fir bears S.78°E. 10.4 ft. scribed ¼ S23 CS BT

Fd. Ok 6/1981, H. Johnstone, M87-74

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 12/2013 - C.S. File 65/80-62

Found - DCSO Brass cap (properly mkd)
18" Fir (snag 7' tall) N.62°E., 10.6 ft. with scar.
14" Fir (snag 8' tall) S.78°E., 10.4 ft. with scar.
16" Fir S.20°E.,. 7.9 ft. good scar.
All trees badly burnt.
New - Set alum. post 2' south
Note - Area badly burnt 8/2013
Compass decl. 15°E.