TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8137)

Set a stone 14x12x10", 8" in the ground, marked ¼ on W side for the ¼ sec. cor., from which
A fir, 10" dia., bears N.74°E., 33 lks., mkd: ¼ S BT.
A fir, 30" dia., bears N.36°W., 40 lks., mkd: ¼ S BT.

BLM dependent resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Survey Technician, under Group #350, surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 32 Page(s) 13200-1)

The ¼ sec. cor. of secs. 9 and 10, determined at record distance from the original bearing trees:
A fir, 15" dia., bears N.72°E., 33 lks. mkd. BT on old bark blaze.(Record bearing, N.74°E.)
A fir, 37" dia., bears N.61½°W., 40 lks., mkd. ¼ S BT on old bark blaze. Remarked ¼ S9 BT. (Record bearing, N.36°W.)
At the corner point
Set an iron post, 28", long, 2½" dia., 22" in the ground, with brass cap mkd. ¼

S 9 | S 10
T31S | R8W
1961

from which a new bearing tree
A fir, 45" dia., bears S.56°E., 72 lks., mkd. ¼ S10 BT.

Troy Rambo - For: Seneca Jones Timber Co. - 7/2005 - M148-7

Found - 1961 BLM brass cap
Rec. 37" Fir - in good condition.
Rec. 45" Fir - in good condition.
Rec. 15" Fir - in good condition.
New - Scribed "¼ S9 BT" on 8" DF, bears S.83°W. 27.4 ft.