TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8372)

Set ¼ sec. post, from which
A Fir, 24" dia., bears N.80°W., 15 lks.
A Fir, 10" dia., bears S.70°E., 25 lks.

Douglas Co. Surveyors Office - George Wenderoth, Deputy - H. Formand Witness - June 1950 - M27-15

Found 36" Fir N.80°W., 9.9 ft.
Drive 1" I.Pipe
Scribe 12" Yew S.26°40'E., 31.8 ft.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-48

Found - No trace of I.Pipe due to Cat, trail over corner point. 1950
Orig. 36" D.Fir, now Snag, N.80°W., 9.9 ft., scribe visible.
10", now 18" D.Fir, S.70°E. 16.5 ft., tree prev. opened, pitched over, scribe visible.
12", now 12" Yew, S.26½°E. 31.8 ft., scribe visible.

Set - Brass Cap at Cor. mkd: County Surveyors T32S R3W
Office
1969
¼ S 6 / S 7

New BT - 8" Hemlock N.5°W. 10.4 ft. mkd: "¼ S6 CS BT".
Orig. call on creek at 44.40 ch. running east, not good, as main creek has moved southward. Call on Snow Ck. of 49.40 ch. is good.