TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 5 & 6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8370)

Set ¼ Sec. post from which
A Fir, 36" dia., bears S.80°E., 8 lks.
A Fir, 5" dia., bears S.36°W., 31 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - For: Douglas Co Road Dept - Jan/Feb 1957 - Rd Drawer (CS)48/Rd #36

Found - Both Orig. BTs., good condition, scribing visible, check for bearings & distances.
The SE BT Orig. bark scribed. I open SW BT good scribe marks.
Set Brass Cap at corner mkd S6|S5 T32S R3W County Surveyors Office, 1957
I Scribe 10" pine N.23°W. 22.2 ft. ¼ S6 CS BT.
I Re-bark scribe Orig. BT. 36" Fir, now 48", ¼ S5 CS BT S.80°E. 5.3 ft. (measured to face.)

Fd. Ok by L. Herzstein, USFS - 7/16/1981 - C.S. File 61/27-23