TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12 of T32-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - George W. Hyde and Wells Lake, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8555)

Set qr. sec. post on E. slope, from which
A Cedar 24" dia., bears S.11°E., 49 lks.
A Cedar 24" dia., bears S.78°W., 24 lks.

Douglas Co. Surveyors Office - James Bryon, Deputy - Milo Godfrey, S.A. Bilow, crew - June 24, 1959 - C.S. File 49/91-7

Found - Both orig. BTs, each BT not completely grown over, show good scribing "BT" - "BT"

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S
¼
R6W S12|S7 R5W
1959

Original BTs are thus from corner:
44" Cedar bears S.11°E., 33.3 ft.
36" Cedar bears S.81°W., 16.8 ft.
I do not rescribe BTs.

Survey by Ronald Brandt for: The Robert Dollar Company - Nov. 1972 - C.S. File 55/257-1

Found - 1959 DCSO brass cap destroyed.
Orig. 44" I.Cedar, S.11°E., 33.3 ft.
Orig. 36" I.Cedar S.81°W., 16.8ft.

New BTs -5.52" D.Fir S.68°15'W., 31.05 ft. mkd. ¼ S12 PS 841 BT.
9.55" D.Fir N.06°40'E., 16.76 ft. mkd. ¼ S7 PS 841 BT.

Bent pipe and brass cap removed, the pipe straightened and then reset in its initial position. The tree measurements are at DBH and horizontal distance from monument to the center of the scribed face.

Found 2½" cap buried 2 feet below ground level on east fill slope of dirt cat road, by K. Hoffine, Nov. 2002 - M141-34