TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; and S.35 of T31-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by WH Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 19 Pgs 8024-25)

Set a Laurel post, 4 ft. long, 4" sq., 20" in ground marked ¼ S on N. side for the ¼ sec. cor., from which
A Live Oak 8" dia., bears S.55°E., 16 lks. mkd. ¼ S BT.
A Fir 24" dia., bears N.10°W., 48 lks. mkd. ¼ S BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531, surveyed Oct. 1963\June 1964 (DCSO records Vol. 33 Page(s) 13617-18)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:
A Fir 45" dia., bears N.10°W., 48 lks. dist., mkd. BT on bark blaze.
A rotted Live Oak stump, size indeterminate, bears S.55°E., 16 lks. dist., with no marks remaining.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 31 S R 7 W

¼ S 35 / S 2

T 32 S R 7 W
1964

from which new bearing trees:
A Fir 19" dia., bears N.44½°E., 38 lks., mkd. ¼ S35 BT.
A Fir 16" dia., bears S.5°W., 68 lks., mkd. ¼ S2 BT

Cor. Fd. and used in BLM survey by Jelley, in 1982 (DCSO records, Vol. 46 Page 17569)

Mark Heimburger - Crew: Bartt Heichel & Anthony Welch - 2/2018 - C.S. File 65/101-44

Found - 2½" iron pipe with 2½" brass cap from which a:
Rooted Live Oak Stump with no visible face bears S.55°E., 10.6'
16" D.fir (now 17" stump) with healed face bears S.5°W., 44.9'
45" (now 48") D.fir with healed face bears N.10°W., 31.7'
19" D.fir (now 20" wind fall) with healed face bears N.45°E., 25.0'
New - 12" Live Oak scribed "¼ S2 BT" bears S.60°E., 10.6'
4" D.fir scribed "X BT" bears S.5°E., 10.5'
28" D.fir scribed "¼ S35 BT" bears N.61°W., 43.0'