TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8807)

A sugar pine, 60" dia., which I marked ¼S on N side for the ¼ sec. cor., and from which
A fir, 20" dia., bears S.40°E., 34 lks., mkd: ¼ S BT.
A fir, 24" dia., bears N.30°W., 49 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - April/May 1968 - C.S. File 54/65-52

Found - Orig. 6" pine corner tree, now snag, old "X" & cruiser's marks.
Orig. 24" D.Fir, now down & rotten, N.30°W., 32.3 ft, found part of "¼" scribe on bark under tree.
No trace of SE BT.

Set brass cap on N side of pine snag mkd: T32S R8W
County Surveyors Office 1968 ¼ S 15 / S 22

New BTs- 8" tan oak N.30°W., 40.1 ft. mkd: ¼ S15 CS BT.
22" D.Fir S.30°W., 39.0 ft., mkd: ¼ S22 CS BT.

Mark Smalley - Roseburg Forest Products - Nov. 7, 1996 - C.S. 65/15-7A

Found - I.P. B.C. - original corner tree crumbling
8" tan Oak, N.30°W. 40.1' good healed scribe visible
22" Fir, S.30°W., 39.0', good - healed face

New - 8" Fir, S.71°W., 18.9' scribed "¼ BT"
5" Fir, N.44°W., 23.8' scribed "¼ BT"

Ron Quimby - Crew: J. Leonard & N. Fromdahl - 11/2013 - C.S. File 65/80-40

Found - DCSO I.Pipe & brass cap (properly mkd)
10" Tan Oak N.30°W., 40.1 ft. vis. scribes
39" Fir S.30°W., 39.0 ft. healed face.
14" Fir S.71°W., 18.9 ft. healed face.
10" Fir N.44°W., 23.8 ft. healed face.

New - Set alum. post 2' east.
Re-tag bearing trees.

Note - Area burnt 8/2013
Compass decl. 15°E.