TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8794)

Set a laurel post, 40" long, 4" sq., 20" in the ground for the ¼ sec. cor. marked ¼S on W side, and from which
A laurel, 8" dia., bears S.65°E., 9 lks., mkd: ¼ S BT.
A fir, 30" dia., bears N.55°W., 13 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John Powell - May 1968 - C.S. File 54/65-65-66

Reported as not found.
Found probably BT. Large D.Fir, old cruisers mk's. Tree now windfall, bark badly burnt. Other BT small laurel gone. Approx Cor. hits call on small creek 2.60 chains fair, but no evidence.

BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor under Group No. 2179, surveyed July/Nov. 2007 - (DCSO records, Vol. 55 Page(s) 21615)

Point for the ¼ sec. cor. of secs. 34 & 35, at proportionate distance, there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd. T32S R8W

¼
S 34|S 35
2007

from which
A fir, 12" dia., bears S.47¼°E., 17.3 ft., mkd. ¼ S35 BT.
A tan oak, 11" dia., bears S.33°W., 5.6 ft., mkd. ¼ S34 BT
Deposit a magnet in a white plastic case at the base of the stainless steel post.