TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8987)

Set a post, 3" sq., 3 ft. long, 24" in the ground, for ¼ sec. cor. marked ¼ S on W. side, from which

A Fir 18" dia., bears N.7°30'E., 66 lks. dist., marked ¼ S BT.

A Fir 16" dia., bears S.54°W., 47 lks. dist., marked ¼ S BT.

BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #'s 350 and 818, surveyed Aug. 1973/May 1974 - (DCSO records Vol. 38 Page(s) 15633)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:

A root hole bears N.7½°E.. 66 lks., with a down Fir alongside 27" dia., with scribe marks ¼ S visible on partially open blaze.

A root hole, bears S.54°W., 47 lks.

At the corner point

Set an iron post, 28 ins. long, 2½" dia., 22" in the ground, with brass cap marked T 33 S R 5 W

¼

S 5 | S 4

1974

from which new bearing trees

A Fir 36" dia., bears S.67°E., 82½ lks., mkd. ¼ S4 BT.

A Fir 16" dia., bears S.26½°W., 35 lks., mkd. ¼ S5 BT.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCSO records Vol. 59 Page(s) 24141)

The ¼ sec. cor. of secs. 4 and 5, reported by Roseberry and Evans in 1973-74, monumented with an iron post, 2½" dia., firmly set, projecting 7" above the ground, with brass cap (Properly) mkd.

from which bearing trees reported by Roseberry and Evans

A fir, 45" dia., bears S.67°E., 54.5 ft., with a healed blaze.

A fir, 32" dia., bears S.26½°W., 23.1 ft., with a healed blaze.

The geographic position in NAO 1983 (2011)

Latitude: 42°43'55.46" N. Longitude: 123°18'33.07" W.