11624

Retracement Subdivisions, T. 30 S., R. 7 W.

CHAINS

A white fir, 24 ins. diam., bears S. 61° W., 30 lks. dist., mkd. ¼ S 32 BT. (New B. T.)

The true course and length of this line is S. 0°20' E., 39.15 chs.

I continue my measurement from the ¼ sec. cor. South, surveying the line bet. secs. 32 and 33.

47.95 Smith Creek, 3 lks. wide, course SE.; ascend.

48.90 Foot of bluffs, bears NW. and SE.

53.55 After diligent search I fail to find any evidence of the old witness cor.

59.65 Top of bluffs, 200 ft. high, continue ascent.

65.75 Summit of ridge, bears NW. and SE.; leave timber; descend.

79.20 Intersect the cor. of secs. 32 and 33, heretofore described.

Land, level mountainous.
Soil, gravelly black loam and rock, 3rd and 4th rate.
Timber, fir, yellow pine and live oak.
Undergrowth, live oak, arrowwood and fir.

Boundaries of T. 30 S., R. 7 W.
Latitudes, departures and closing errors

Line designated	True bearing	Dist.	Latitudes N.	Latitudes S.	Departures E.	Departures W.
			Chs.	Chs.	Chs.	Chs.
W. bdy. sec. 31	(N. 1°21' W.	39.18	39.17			0.92
	(N. 0°30' E.	38.24	38.24		0.34	
N. bdy. sec. 31	(N. 87°20' E.	43.04	2.00		42.99	
	(N. 87°14' E.	39.38	1.89		39.33	
N. bdy. sec. 32	(N. 89°42' E.	37.23	0.19		37.23	
	(N. 89°22' E.	38.63	0.43		38.63	
N. bdy. sec. 33	(N. 89°28' E.	40.07	0.37		40.07	
	(N. 89°45' E.	39.67	0.17		39.67	
E. bdy. sec. 33	(S. 1°21' W.	39.74		39.73		0.94
	(S. 0°36' W.	39.43		39.43		0.41
S. bdy. sec. 33	(N. 89°13' W.	39.37	0.54			39.37
	(S. 88°18' W.	39.09		1.14		39.07
S. bdy. sec. 32	S. 88°18' W.	76.72		2.28		76.69
S. bdy. sec. 31	(S. 88°18' W.	2.77		0.08		2.77
	(S. 89°58' W.	40.80		0.02		40.80
	(S. 89°05' W.	38.11		0.61		38.10
Convergency	.....	.....	.....	.....	0.07	
	Totals		83.00	83.29	238.33	239.07
				83.00		238.33
	Error in Lat.			0.29		
	Error in Dep.					0.74

General Description

This portion of the township is mountainous broken land covered with heavy fir, yellow pine, live oak, white oak, black oak and myrtle, with dense undergrowth of same, including tan oak and arrowwood.

The mineral appears to be chromium and placer gold along the creeks.

There is some good agricultural land to be found along the creeks.

There are no settlers in this portion of the township. The Paul Sphoon homestead in sec. 32 has been abandoned.

April 18, 1918.