County Surveyor's Record, Douglas County, Oregon

15383

T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

During August 1966 the Oxbow Ridge fire swept across a portion of township 20 south, range 9 west, destroying the undergrowth and killing much of the standing timber. To help meet the administrative needs in the burned area an aerial electronic cadastral resurvey project was conducted jointly by the Oregon State Office Branch of Cadastral Engineering and the Research Branch of the Portland Service Center in the spring of 1967. This project also served to test the limitation and feasability of adopting this type of survey to the terrain found in western Oregon.

In the course of placing panels at corners for sighting from the air, many corners were remonumented or rehabilitated. the record of the action taken at the corners and control points for the portion of the project in this township are included in this set of notes. Newand live bearing trees were marked at the corners where possible. In cases where no live trees were available trees previously used as accessories were remarked on a new blaze, and in situations where the timber had been logged it was necessary to use stumps for corner accessories. Steel fence posts were set alongside the corner monuments to aid in the protection and perpetuation of the corner.

The following field notes describe the remonumetation of certain original corner points, towmship 20 south, range 9 west, Willamette Meridian, Oregon, as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories Followed by Remonumentation of Corner Points, with New Accessories when Needed".

The mean magnetic declination is 20° 30' E.

Subdivisons, T. 20 S., R. 9 W.,
Willamette Meridian, Oregon

(Rehabilitating corners established by
William Thiel, in 1891, and remonumented by
Thomas A. Tillman and Joseph S. Gawron, in 1954)

The 1/4 sec. cor. of secs. 25 and 26, monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.

1/4
S 26 | S 25
1954

OK. ROBERTS

Fd. by LES 2/27/84 M 96-20

from which the original bearing trees

A fir, 57 ins. diam., bears N. 83° E., 47 1/2 lks. dist., with healed blaze. (Record, 45 lks.)

A fir, 55 ins. diam., bears N. 51° W., 26 lks. dist., no marks visible on burned blaze. Rescribed 1/4 S 26 BT on new blaze. (Record, 20 lks.)

and the remains of the bearing trees marked in 1954
A hemlock, 10 ins. diam., bears S. 73 1/2° E., 11 1/2 lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Record, S. 76° E., 11 lks.)