32-8

Frank Cain Dep. Cor.
Wit. { G. E. Daniels
F. A. McMains
G. C. McCoon
J. B. Barry
Mar. 14, 1920

Cor. Secs. 1-2-11-12 Re-Established by setting a 1"x 36" Iron Pipe from which
a fir 32" brs N. 10° W. 72 Lks.
a " 28" " S. 26° E. 80 Lks.
a " 36" " S. 20° W. 66 Lks. Original B. T.

F. C. Frear
Wit { J H Wolford
R D Wolford
Oct 19, 1934

The Cor. on the North Line of T. 33 S, R. 7 W. Between Secs. 1 & 2. I Reset with 2½"x 4' Drive Shaft from which A Cedar brs S 35° E 20 lks No Marks; Fir Brs S 44° W 28 lks No Marks. Fir Brs. N 66° W 21 lks No Marks. All Trees check notes but are badly burned & Rotted, however this Cor. is 708 ft. East of the Cor. on the S. Line of T. 32 S. R. 7 W. which also checks close.