Douglas County Surveyor's Record of Government Corners Renewed

T 25 T.S. 2 E R. E W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

CONT - -
J. Landrum, USFS
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein
5/12 C.S. 62/10

No new monument set. **8**
New BT - A 20" D. fir, N.34°W., 23.1 ft. scribed "T25S R1E S25 CSBT" on a single blaze.
Note - Corner is located on a steep NW slope, approx. 5/12/83 on the end of U.S.F.S. Road #4760-400.

Jim Landrum, USFS
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein
Oct. 31, 1983
C.S. 62/10

1/4 Corner for Secs. 15 and 22. **9**
Found - 1928 GLO brass cap on 1" diam. I.P. 36" long, lying on ground. Cap properly mkd.
24" hemlock stump, S.44°W., 6.4 ft. (Rec. S.21°E. 4.6 ft.) with scribe marks "1/4 2 T" visible on partially healed blaze. (Blaze facing N.44°E. for a SW BT.)
30" hemlock stump, N.6°W., 66.0 ft. with scribe marks "1/4 S BT" visible on partially healed blaze.
Set - Distance-distance from the center of the BTs would not intersect; and from the faces of the BTs would not match the blazed faces. At record bearing & distance from the orig. NW BT and from the direction of the face on the orig. SW (Rec. SE) BT, I RESET I.P. 30" in the ground in a 3 ft. mound of stone. I stamp "RESET 1983 CS" on brass cap.
New BTs - 5" hemlock, N.53°E., 13.0 ft. scribed "1/4 S15 CS BT" on single blaze.
12' x 20' x 8' high rock outcrop, S.42°W., 55.2 ft. marked "X BO" on highest point (along north edge).
Note - Corner is in USFS clearcut 25-2-15-1, approx. 130 ft. east and 200 ft. north of Reynolds Ck. 10/31/83

Maurice E. Farr,
U.S. Forest Service
Leonard Herzstein
May 8, 1984
C.S. 62/15

1/4 Section Corner for Secs. 21, & 22. **10**
Found - Orig. 1" I.Post bent flush with the grnd. w/properly marked Brass Cap... Dug up I.P.--- Orig. 1928.
now 30" long w/top 12" bent over 60° w/bottom 18" still vertical in ground. I use the vertical position of the base as the orig. position of the corner, from which the remains of the orig. BTs:
BTs - 18" D.Fir stump w/log alongside bears S.62°E.,38.5-ft. (Rec. 38.9-ft.), with healed blaze.
12" D.Fir snag bears S.30°W.,7.9-ft. w/healed blaze.
Set - I reset orig. mon.over orig. vert. position. Since I could not straighten the I.P., I buried the base, bent to north, & the top is set vert. & flush in a 3-ft. d. mound of stone.
6-ft. steel fence post about 2-1/2-ft. north of corner with USFS sign #54-4 attached.
New BTs - 20" I.Cedar bears S.39-3/4°E.,75.2-ft., scribed: 1/4 S22 BT, on a single blaze.
4" W.Fir bears N.54-3/4°W.,48.9-ft., scribed: 1/4 S21 BT, on a single blaze.
Note - Corner is 40-ft. north of new road (USFS Rd.#3816-150), 0.3 miles from jct. with USFS Rd.#3816-100. 5/84

Douglas County
Surveyors Office
S. J. Flause and
R. W. Smith, Deputies
March 30, 1988
C. S. 62/50 - 9

1/4 Corner for Sections 10 and 11 **11**
Found - Rotted remains of cedar stump protruding approx. 6" above ground from dead but sound cedar roots. Growth pattern supported a small tree.
Area has been logged and burned. No evidence is found of the scribed trunk of the corner tree.
Orig. BT, a cedar 10" dia. now a 16" DBH fallen and burned cedar with partial illegible scribing visible on a previously opened and now burned blaze. The well defined root-hole of this tree bear N.59°E., 12.5 ft. (As per record)
No evidence is found of the original northwest bearing tree.
All new accessories from Renewal #5 found:
A 5/8" x 36" I. rod with a 1½" alum. cap stamped "S80-30W 70.7' R.M." with an arrow pointing toward the corner position is firmly set and protrudes approx. 7" above ground & bears N.74°E., 70.7' (Rec. N.80°30'E., 70.7 ft.)
A 17" cedar now a 19" DBH incense cedar with the scribing "1/4 S11 CS BT" visible in a partially healed double blaze bears N.14°E., 56.1 ft. dist. (Rec. N.18°E., 56.1 ft.)
A 5/8" x 36" I. Rod with a 1½" alum. cap stamped "S47-30W 64.9 ft. R.M." with an arrow pointing toward the corner position is firmly

CONT. NEXT PAGE