Douglas County Surveyor's Record of Government Corners Renewed

T20S T. S. R 9 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21991

Donald Branch
International Paper Co.
2-3-87
M101 - 14
C.S. 63-48

60

1/4 Corner for Section 12 only.
Found : A 1" Pipe with 2" BLM Cap buried 6" in the ground marked "T20S R9W | R8W , 1/4 S12| 1954. Set Witness post with attention sign.
BT's : A 16" Hemlock (down)bears S 74°W, 21'± to hole. With blaze and BT tag.
50" Fir bears N41 1/2°W, 19.7 ft. With signs.
New BT's: 8" Hemlock bears S5°E, 16.0 ft. Scribed "1/4 S7 BT".
Note : Monument is at toe of fill of road 50' West .

61

1/4 Corner for Sections 26 and 35
(Note: Corner previously referenced out Aug. 21, 1985. See C.S. 63/50 for reference notes.)
CORNER REPORT
Found - 1953 GLO brass cap pulled out of ground by recent logging activity
24" Fir stump, S.36°W., 8.0 ft. 1953 BT. (Rec. S.36 3/4°W., 7.9 ft)
38" Fir stump, N.45°E., 6.1 ft. 1953 BT. (Rec. N.45½°E., 5.9 ft.)
Set - Re-set 1953 GLO brass cap firmly in ground using "P.K." nails set in 8/21/85. Buried purple magnetic marker under iron pipe.
Set metal fence pose, with survey attention sign wired to, beside brass cap. Painted BT stumps red.
No new accessories. Corner lies on flat ground about 150 ft. North of Smith River Road.

9/14/87

62

1/4 Corner for Sections 29 and 30.
(Note: Corner previously reference out Aug. 21, 1985. See C.S. 63/50 for reference notes.)
CORNER REPORT
Found - 1953 GLO brass cap bent over from recent logging activity.
60" Fir stump, N.43°W., 60.5 ft. (no marks) 1877 BT(record N.44½°W., 58.1 ft.)
20" maple, S.39°E., 22.1 ft. (scar visible) 1953 BT.(record S.36°E., 23.1 ft.)
24" maple, N.53°W., 60.4 ft. (scribe vis.) 1953 BT. Rec. N.53°W., 59.4 ft.)
24" cedar, S.05°W., 34.0 ft. to 6" spike in base. 8/21/85 R.P.
40" maple, N.74°W., 68.6 ft. to 6" spike in base. 8/21/85 R.P.
Set - RE-set 1953 GLO brass cap firmly in ground using distances of 34 ft. and 68.6 ft. from 6" spikes set in 8/21/85. Buried purple magnetic ;marker under iron pipe.
Set alum. fence post,with land survey monument sign attatched to, beside brass cap. Painted all BTs red.
New Accessories:
Drove 6" spikes into base of 1953 GLO bearing trees.
20" maple S.39°E., 21.8 ft. to 6" spike.
24" maple, N.53°W., 61.2 ft. to 6" spike.
Corner lies about 150 ft. North of Bear Creek and about 30 ft. East of small side creek.

Les Roberts, L. S. No. 1039
November 14,1987
C.S. 63/50

9/14/87

63

Reference Monument to SW Corner Section 28.
(Note: Corner previously referenced out Nov. 4, 1985. See C.S. 63/50 for reference notes.)
CORNER REPORT
Found - NE Reference monument has been up-rooted by recent logging activity.
1953 GLO brass cap R.M. bears S.44° 53' 45" W., 59.04 ft.
37" Fir, S.49½°W., 54.5 ft. (scar vis.) 1953 BT. Rec. S.50°W., 54.8 ft.
40" Fir stump, N.06°W., 115.5 ft. (scar vis.) 1953 BT. Rec. N.13 3/4°W., 115.5 ft.
49" fir stump, S.73½°E., 70.0 ft. scar vis., 1953 BT. Rec. S.73½°E. 70.0 ft.)
49" fir stump, N.84½°E., 84.7 ft. scar vis. No record.
54" fir stump, N.44½°E., 80.4 ft. 1953 BT. Rec. N.44½°E., 80.5 ft.
Set - Re-set N.E. reference monument using "P.K." nail R.P.'s set on 11/4/85. Buried purple magnetic marker under iron pipe.
Set metal fence post, with land survey monument sign attached to, beside brass cap.

9/14/87