Douglas County Surveyor's Record of Government Corners Renewed

20 T. S. 10 R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 21991

104

WEST
1/4 Section Corner to Section 19 Only.
SET - 3 1/2" x 30" Aluminum flared pipe with Alum. cap., Stamped: T20S R11W R10W 1/4 S19 1984 PLS 1922
BT's - 7" D. Fir, bears S.10°E., 2.4 ft. dist., scribed 1/4 S19 BT.
10" D. Fir, bears N.38°E., 21.2 ft. dist., scribed 1/4 S19 BT.

Michael J. Schwartz, & L.W. Hunnemuller
RPLS #1922 RPLW #1050
Sulphur Cadastral Survey - Siuslaw Natl. Forest
U.S. Forest Service
October, 1985
M 99 - 79 A & B

105

Section Corner to Secs. 17, 18, 19, & 20 Renewal #24
Found - Douglas Co. Brasscap, marked T20S S17 S18 S19 S20 R10W 1968.
BT's - 19" Hemlock stub, bears N.69 1/2°E 36.0 ft. dist. (1968) Badly decayed.
30" rotted hemlock stub, bears S.31°E., 4.2 ft. dist., with axe marks.
10" Alder, bears N.84°E., 43.2 ft. dist., with partially healed face and scribing visible. (Record, N.84°E., 43.6 ft. 1968)
10" Hemlock, bears N.48°W., 10.0 ft. with healed face. (Record, N.48°W., 10.0 ft. 1968)
15" D. Fir, bears S.48°W., 28.4 ft. with pitch over face. (Record, S.48°W., 28.4 ft. 1968)
NEW BT's - 8" Hemlock, bears S.42°E., 4.1 ft. dist., scribed: T20S R10W S20 BT.

FD BC
BY Shaner
4/1/93
1993-0072 A&B

106

1/4 Corner for Sections 33 and 28
Found - Brass cap/iron pipe in good condition. Ren. No. 77
68" D. fir stump, scribing visible, bears S.02°W., 19.5 ft.
24" D. fir BT of record, uprooted and slid down slope.
New BT - 18" D. fir stump with IPCO tag and nail bears N.33°E., 17.4 ft.
6/5/86

W. Carey Weatherly
L.S. 1667
For: International Paper Co.
June 5, 1986
.S. 63/37

107

Section corner for Sections 29, 30, 31 and 32
Found - Iron pipe/brass cap, GLO 1951 Ren. #21
12" fir bears North, 53.2 ft. closed face
12" maple bears S.67°E., 28.8 ft.
24" cedar bears S.49°W., 7.9 ft. closed face
New BT - 16" fir bears N.23°00'00"W., 37.0 ft. scribed S30 BT.

R hard J. Hintz
Fo.: International Paper Co.
Sept. 1985
M 99 - 51

108

1/4 Corner for Sections 19 and 30
Found - 1½" iron pipe with brass cap. Ren. #90
14" fir, S.48¼°E., 30.3 ft. (closed face)
22" cedar, N.61°W., 46.1 ft. (closed face)
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap as a reference point bears S.0°16'53"W., 35.75 ft. Cap stamped "T20S R10W 1/4 S19 S30 PLS 1978 1986 35.75 N0°16'53"E"

109

1/4 Corner for Secs. 29 and 30.
Found - Boat spike with "X" in top in center of rotted fir stump. Ren.#55
14" rotted hemlock stump, N.6°E., 9.5 ft. (no record)
30" rotted hemlock stump, N.40½°E., 34.1 ft.
20"hemlock, N.56°E., 40.6 ft. (scribe visible)
36" fir stump, S.52°E., 26.4 ft. (U.S.F.S. tag - not of rec.)
Set - I referenced the boat spike, then pulled it and replaced it with a 5/8" x 27" rebar with 3" alum. cap marked "T20S R10W 1/4 S30 S29 PLS 1978 1986".

Daniel Baker LS 1978
For: U. S. Forest Service
June 10, 1986
M 102 - 12

110

Center 1/4 Corner for Section 30
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap marked " T20S R10W C 1/4±S30 PLS 1978 1986"
New BTs - 10" hemlock, S.87°E., 26.9 ft. scribed "C 1/4 S30 BT"
16" cedar, N.4¼°W., 51.0 ft. scribed "C 1/4 S30 BT".
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap as a reference monument bears N.0°16'53", 38 ft.

FD. OK
7/92
Royce Hill
M 115-71