Douglas County Surveyor's Record of Government Corners Renewed

T 21 T.S. R 4 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

153

1/4 Corner for Section 6; and Sec. 31 of T.20-4
CORNER REPORT ONLY
Found - 1968 Douglas County Brass cap. Ren. #91 and 98
24" fir, N.18°E., 14.2 ft. scar visible. 1958 BT. (WEYCO record is N.18°W.)
60" fir stump, S.37°W., 54.2 ft. scar vis. 1958 BT.
14" fir stump, S.56°W., 55.3 ft. scar vis. 1968 BT
20" fir, N.33°W., 16.3 ft. scar visible. 1968 BT.

Les Roberts
For: Seneca Timber
June, 1990
M 110 - 29

6/11/90

FD OK Les Roberts 4/94 M123-SC154

Section Corner for Sections 10, 11, 14, and 15
Set - 2" X 41" iron pipe with brass cap with 6' steel fence post 2' south.
New Bt's - 11" Fir, N.71°E, 114.2' scribed "T21SR4WS11BT"
23" Fir, S76½°E, 118.3' Scribed "T21SR4Ws14BT"
18" Maple, S41°W, 33.0' scribed "T21SR4WS15BT"
18" Double Alder, N13°W, 46.5' bark scribed "T21SR4WS10BT"

Donald Peel
For: Weyerhaeuser
Oct. 1990
M 110 - 72

10/90

155

1/4 Corner for Section ~~6~~ 11 and Section 14.
CORNER REPORT ONLY
Found - 5/8" rebar
21" Fir, S63 3/4°E, 13.7' Closed face
48" Fir stump, S43½°W 42.9' scribing visible on pitch face "BT"
Note - 1" (O.D.) iron pipe bears N66° 01' 40"E, 5.73'

10/90

1/4 Corner for Section 14 and Section 15
Set - 2" X 42" iron pipe with brass cap 6' steel fence post 1' south
Bt's - 16" Alder, N.63½°E., 22.8' bark scribed "¼S14BT"
13" Alder, S.66 3/4°E.,31.2' bark scribed"¼S14BT"
60" Fir stump, S.73½°W., 41.0' scribed "¼S15BT"
12" Cedar, N.51 3/4°W.,34.2' scribed "¼S15BT"
Note - 1/2" rebar of unknown origin found near 1/4 corner bears S.01° 41' 30" W., 34.55'

156

10/90

1/4 Corner for Section 10 and Section 15
Set - 2" X 41" iron pipe with brass cap
Bt's - 24" Maple, N.85½°E., 51.3' scribed "¼S10BT"
48" White Fir, S.26°E, 32.0' scribed "¼S15BT"
32" White Fir, S.20¼°W., 74.4' scribed "¼S15BT"
24" Hemlock, N.31½°W., 55.9" scribed "¼S10BT"
Note - 3/4" iron pipe of unknown origin bears S 08° 56'07" E 38.54'

157

10/90

Center 1/4 for section 29.
Found - 5/8" iron rod without cap.
BT's - 12" fir blaze healed N.14°W., 6.3 ft. (rec. N.16°W., 6.0 ft.)
6" fir blaze healed S.46°E., 14.5 ft. (rec.S.46°E., 14.4 ft.)
New BTs 8" fir, face blazed N.62°E., 17.7 ft. Ren. # 117
6" fir, face blazed S.24°W., 17.0 ft.
Note - Painted new and old blazes red, and painted red bands around all Bts

Dennis Findorff
L.S. 2424
For: M. Holleman
Jan. 1991
M 111 - 46
C.S. 63/129

1/91

158

Section Corner for 25, 26, 35 and 36
Found - No evidence of orig. or renewal from 1955 monuments found. (Ren.26)
1958 BLM brass cap on a 2½" O.D. Iron pipe firmly set and protruding 6" above ground.
No evidence of original BTs found.
Bearing trees from Ren. #26 evident but not checked. (BLM did not accept G.A. Gardner's corner position.)
Bearing trees from 1958 BLM Resurvey found as follows:
A Fir 8" dia. now a 15" D.B.H. 6 ft. tall Fir stump with a fully healed single blaze bears N.32°E., 28.4 ft. (Rec. N.32°E 31.7 ft.) (possible error in record links measurement)
A Fir 14" dia. now 22" D.B.H 5 ft. tall Fir stump with a fully healed single blaze bears S.55°E., 31.0 ft. (as per record)

Doug. Co. Surveyors Office
R.W. Smith; S.J. Flause
November 13, 1991
C.S. 64/21

159

C O N T. N E X T P A G E