Douglas County Surveyor's Record of Government Corners Renewed

T 21 T. S. R 10 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

106

North 1/4 Corner for Section 17 only.
Found - 1" I.P. filled with concrete and broken off, a 2 1/2" brass cap properly mkd. lying alongside. (1919)
70" D. fir bears S.72°W., 14.5 ft. (to center of tree) well healed scar.
36" alder windfall, roothole bears S.12°E., 15.2 ft.
Set - 2 1/2" x 30" alum. pipe over found I.P. with 3 1/4" alum. cap mkd. "USDA Forest Service 1/4 S17 RLS 1651 1984 Unlawful to Disturb". Buried brass cap alongside.
New BT - 34" D. fir bears S.71°E., 58.4 ft. blazed and scribed "1/4 S17 BT".

Herman Pieske RLS #1651
A A Surveying Company
For: U. S. Forest Service
Nov. 1984
M 97 - 74 A & B

107

South 1/4 Corner Section 8 only.
Set - At proper position, 2 1/2" x 30" alum. pipe, 26" in the ground, with sandstone mound, with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W S8 1/4 RLS 1651 1984 Unlawful to Disturb".
New BTs - 16" hemlock bears N.88°W., 36.3 ft. blazed and scribed "1/4 S8 BT"
12" D. fir bears N.79°E., 55.8 ft. blazed and scribed "1/4 S8 BT".

108

Southeast corner Section 7.
Found - 2" iron pipe with 2 1/2" brass cap properly mkd. (1919)
46" D. Fir bears N.87°W., 38.9 ft. shows good scar.
New BT - 40" maple bears S.15°E., 20.8 blazed and sribed "T21S R10W S17 BT"

109

1/4 Corner for Section 6; and Sec. 31 of T.20-10
Set - 2 1/2" x 30" alum. pipe with 3 1/4" alum. cap mkd. "U.S. Dep of Agri-Forest Service T20S R10W S31 1/4 S6 T21S RLS 1651 1983 Unlawful to Disturb". Set pipe and cap 12" below ground in/pastur
New BTs - 10" alder bears N.85°47'E., 170.7 ft. Bark scribed "1/4 S31 BT".
12" alder bears S.29°10'W., 264.2 ft. Bark scribed "1/4 S6 BT".

Herman Pieske RLS #1651
AA Surveying Company
For: U. S. Forest Service
November 1984
M 97 - 76 A & B

110

1/4 Corner for Section 6; and Section 1 of T.21-11
Set - At proper position, 2 1/2" x 30" alum. pipe, 28" in the ground with 3 1/4" alum. cap mkd "USDA Forest Service T21S R10W R11W 1/4 S1 S6 1984 RLS 1651 Unlawful to Disturb".
New BTs- 36" hemlock bears N.19°E., 84.8 ft. scribed "1/4 S6 BT" in double blaze.
27" cedar bears N.57°E., 67.2 ft. scribed "1/4 S6 BT" in double blaze.
32" cedar bears N.1°W., 48.6 ft. scribed "1/4 S1 BT".

111

1/4 Corner for Sections 6 and 7
Found - 1" I.P., cap broken off lying alongside. GLO 1919.
36" original fir stump, badly rotted bears S.60°W., 4.2 ft. No face visible.
42" fir stump badly rotted bears N.30°W., 11.1 ft. visible scribes "1/4 S6".
Set - 2 1/2" x 30" alum. pipe, 24" in the ground, with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W 1/4 S6 S7 RLS 1651 1983 Unlawful to disturb". Buried GLO cap alongside.
New BTs- 16" forked D. fir bears N.36°W., 15.3 ft. (8" fork to west) faced and scribed "1/4 S6 BT".
28" D. fir bears S.29°W., 17.5 ft. faced and scribed "1/4 S7 BT".

112

1/4 Corner for Section 7; and Section 12 of T.21-11
Set - 2 1/2" x 30" alum. pipe 22" in the ground with 24" diam. mound of stone, with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W 1/4 R11W S12 S7 1984 RLS 1651 Unlawful to Disturb".
New BTs- 29" D. fir bears S.81°E., 204.6 ft.scribed "1/4 S7 BT".
7" cedar bears S.34°W., 60.4 ft. scribed "1/4 S12 BT".
Set - Reference monument, a 2 1/2" x 30" alum. pipe 26" in the ground with 3 1/4" alum. cap mkd "USDA Forest Service T21S R10W S7 RM N19°40'W 50.85 ft. 1984 RLS 1651 Unlawful to Disurb", bears S.19°40'E., 50.85 ft.

Herman Pieske
RLS #1651
AA Surveying Service
For: U.S. Forest Service
Nov. 1984
M 97 - 77 A & B