Douglas County Surveyor's Record of Government Corners Renewed

T 22 T. S. R 10 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21961

113

East 1/4 Corner Section 36 only of T.22-11
Found - 3" OSBF brass cap 9n an iron pipe, found 5" below ground. Ren. No. 58
Orig. NE BT is gone.
39" now 36" dia. 1½ ft. high D.Fir stump with a fully healed single blaze, bears N.53°W., 31.7 ft. (Rec. N.53°W., 31.0 ft. dist. is a face measurement) Ren. No. 58
32" now 36" dia. 5 ft. high D.Fir stump with a fully healed single blaze, bears S.54½°W., 87.8 ft. (Rec. S.54½°W., 86.8 ft. dist. is a face measurement) Ren. No. 58
New BTs - 30" dia. 4 ft. high D.Fir stump with boat spike through BT tag set on top of stump near center. spike stamped "BO 1" Spike bears N.34°E., 23.0 ft.
32" dia. 5 ft. high D.Fir stump with boat spike through BT tag set on top of stump near center. Spke stamped "BO 2" Spike bears S.74°E., 74°E., 32.0 ft.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 3, 1992
C.S. File 64/24

3/3/92

114

Meander Corner, Sections 6; and 1 of T.22-11
Found - 2½" DCSO brass cap on an iron pipe 3" below ground. Renewal No. 77
18" now 58" dia. broken top spruce, with a rotted center, partially healed, pitched over blaze, with illegible scribing from M 56-56 visible. BT bears S.8°E., 111.5 ft. (agrees with record) Orig. BT.
New BT - 9" dia. Alder, bark scribed "MC S1 CS BT" bears S.9½°W., 104.4 ft

Douglas County
Surveyors Office
Randall Smith
March 5, 1992
C.S. File 64/24

3/5/92

115

1/4 Corner for Section 6 only of T.22-9
Found - No monument found.
22" D.Fir stump 3½ ft. tall, S.27°E., 34.3 ft. (Rec. S.31½°E.) bark removed, sheet metal cap on top.
30" D.Fir stump 2½ ft. tall, N.60°E., 22.8 ft. (Rec. N.58°E.) bark removed, sheet metal cap on top.
Set - 30" x 2¼" Iron post with 2½" brass cap, top 5" above mound of stone at intersection of record distances from found accessories. Cap mkd:

T 22 S
R 10 W R 9 W
¼ S 6
1992 RPLS 811

No new accessories marked.
Corner is located in a newly logged BLM clear-cut (Mill Creek Ridge timber sale Unit #4). It is on very steep (80%) southwest slope about 400 ft. northeast of Little Mill Creek.

Steven P. Ness
L.S. #811
June 26, 1992
C.S. File 63/138

6/26/92

116

Closing Corner for Secs. 30 and 31 only
Found - Original stone, 36" x 20" 10", laying on side with marks CC on top, 5 notches on north edge and + on East edge.
6" now 29" dia. 7 ft. high burnt D.Fir stump, with a fully healed blaze, bears S.65°E., 13.2 ft. (Orig. BT)
8" now 26" dia. 4 ft. high burnt D.Fir stump with a fully healed single blaze, bears N.63°E., 40.8 ft. (Rec. N.63°E., 40.0 ft. Ren. No. 65) Orig. BT.
29" dia. 3 ft. high burnt D.Fir stump with a fully healed blaze, bears S.80°W., 10.0 ft. (Rec. Ren. No. 65, S.75°W., 10.0 ft.)
20" dia. 2 ft. high burnt D.Fir stump with evidence of a healed lower blaze, bears S.33½°E., 43.7 ft. (Rec. S.33½°E., 44.9 ft. possible slope dist. to blaze) Ren. No. 65
No white cedar post from Ren. No. 65 found.
Set - A 2 3/8" dia. brass cap on a 1 3/8" O.D. x 32" long Iron pipe is set at a position determined from bearing trees. BC/IP protrude 4" above ground. Original stone is placed along southerly edge of BC/IP on top of ground. Brass cap marked:

DOUGLAS COUNTY SURVEYORS

		T 22 S		
R 11 W	S 25	S 30 / S 31		R 10 W
		1993 Office		

No new Accessories.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 22, 1993
C.S. File 64/39